



THERMAL VISION AUSTRALIA

Inspection services

A.B.N.86 568 631 384

REPORT ON THERMAL INSPECTION
of the

Building Envelope

At

Any ware st Any ware Victoria 3999

CUSTOMER CODE: 1200

Prepared for:

Client

8TH November 2014

Prepared By

Charles Cassar


Camera Type: FLIR T400

Camera Serial Number: 345001532



9031

S





9031

Date: 8/11/2014

Time: 4:04:30 PM

RESULT TABLE:

Max Temperature	13.0 °C
Sp1 Temperature	8.7 °C

IR_0589.jpg





9031

Date: 8/11/2014

Time: 4:12:08 PM

RESULT TABLE:

Max Temperature	26.1 °C
-----------------	---------

IR_0604.jpg






9031

Date: 8/11/2014

Time: 4:08:40 PM



RESULT TABLE:

Max Temperature	14.3 °C
Sp1 Temperature	13.8 °C

IR_0598.jpg



Insulate door and reseal



9031


Date: 8/11/2014

Time: 4:22:57 PM

RESULT TABLE:

Max Temperature	20.5 °C
-----------------	---------

IR_0613.jpg



Missing insulation
ir0613 page 6



9031



Date: 8/11/2014

Time: 4:23:49 PM

RESULT TABLE:

Max Temperature	20.9 °C
-----------------	---------

IR_0615.jpg



Missing insulation
ir0615 page 7



9031



Date: 8/11/2014

Time: 4:26:22 PM

RESULT TABLE:

Max Temperature	20.8 °C
-----------------	---------

IR_0617.jpg



Missing insulation
ir0617 page 8



9031



Date: 8/11/2014

Time: 4:26:50 PM

RESULT TABLE:

Max Temperature	22.3 °C
-----------------	---------

IR_0619.jpg



Missing insulation
ir0619 page 9



9031


Date: 8/11/2014

Time: 4:31:52 PM

RESULT TABLE:

Max Temperature	36.7 °C
-----------------	---------

IR_0621.jpg



Missing insulation
ir0621 page 10



9031



Date: 8/11/2014

Time: 4:33:56 PM

RESULT TABLE:

Max Temperature	52.3 °C
Sp1 Temperature	19.2 °C
Sp2 Temperature	19.9 °C

IR_0623.jpg



Missing insulation
ir0623 page 11



9031

Date: 8/11/2014

Time: 4:53:07 PM



RESULT TABLE:

Max Temperature	17.9 °C
-----------------	---------

IR_0629.jpg



Insulate door and
reseal

Thank you for the opportunity to carry out the Thermal inspection of your premises and we look forward to our mutual association in the future.

Charles Cassar

Charles Cassar
Thermographer Level 1 Electrician 'A' Class
Electrical Contractor